

SPECIFICATIONS AND PHOTOGRAPHS

Fly Alliance 866-224-5387 | Sales@flyalliance.com





AIRFRAME

Total Time Sine New 30 Hours

Total Landings Since New 15 Landings

Certification FAA Part 135

Maintenance Tracking CAMP **APU**

Honeywell Description

Total Hours Since New 15 Hours

JSSI APU Program

ENGINES

ONE

Pratt & Whitney 545C Description

Total Hours Since New 30 Hours **Total Cycles Since New** 15 Cycles

Both Engines are on JSSI

TWO

Pratt & Whitney 545C Description

Total Hours Since New 30 Hours

Total Cycles Since New 15 Cycles

AVIONICS

Pro Line 21 CNS Radios - Collins

Automatic Direction Finder (ADF) - Collins

2nd Automatic Direction Finder (ADF) - Collins

FMS-3000 with GPS – Collins

2nd FMS-3000 - Collins

FMS Performance Database – Collins

IFIS-5000 - Collins

HF-9031A High Frequency Communications w/Selcal – Collins

VHF Datalink w/Graphical Weather - Collins

VHF Datalink w/Textual Weather - Collins

FA2100 Cockpit Recorder - L-3

Flight Data Recorder (ICAP Type 1A) – L-3

Collins TCAS-4100 w/ Change 7.1

Mark V-A w/RAAS - Honeywell

C406-N ELT – Artex

TWR-850 Turbulence Doppler – Collins

Broadcast Weather – XM

WX-1000E Lightning Detection

EROS MLD20-505 Full-Face Oxygen Masks Pulselite 2401 System Interfaced to TCAS II

10 Person Life Raft



ENTERTAINMENT AND CONNECTIVITY

Airshow/Monitors Airshow

Wi-Fi GoGo Avance L3 Wi-Fi

Sat Phone GoGo ST 4300

Interactive Moving Map Flightpath 3D

INTERIOR

Number of Passengers Nine (9)

Cabin Configuration 9 Pax Executive Interior to include fold-out tables in the club seating area done in shades of light beige leather with complimentary tan patterned carpet

Aft. Belted

Lavatory Locations Forward

Galley Location

EXTERIOR

Painted in March 2023

Matterhorn White with Orange and Blue Accent Stripes











































